



Aa-value approx 1,02m²

Structure tolerances that have to be adhered to for the failure-free operation of the skylights (please see the technical information BKT01 enclosed to our order confirmation)

welding seam: Execution of visible welds according to DIN EN ISO 10042 Limits for irregularities table 1 Rating groups C execution class EXC2	<input type="checkbox"/> Test measurements: function depends on compliance with these test <input type="checkbox"/> Tolerances:	LAMILUX smoke lift rooflight F100W OKD 120/120, K30-"K" 4ABK 24V SHEVVS fitting
Heinrich Strunz GmbH Zehstraße 2 95111 Rehau/Bayern Tel.: (09283) 595-0 Fax: (09283) 595-290	Date: 24.08.2022 Checked: L.Michel	Scale: 1:7 Material



EDV No. H:\Zeichnungen\Sonstiges\Michel\Zeichnungen 2022\IMI_22_045.dwg
 Drawing no.: IMI_22_045-01